coope of	Work for Property Loc			4200 North 19th	1 1444	
	Property is: Single Fan	nily 🗹	Duplex	□ Other □		
Date:	9/8/2014					
take no respo		after the ins	spection da	ate, or for omissions through	the Redevelopment Authority, and their re h error or oversight. The list does not ned programs.	•
Exterior	Condition Report					
Location Site	Required Work Landscaping	n/a ☑	Yes 🗌	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a ✓	Yes 🗌		\$	
	Service walks	n/a ✓	Yes 🗌		\$	
	Fencing	n/a ✓	Yes		\$	
	Parking	n/a ✓	Yes 🗌		\$	
	Retaining walls	n/a	Yes 🗌		\$	
	Other	n/a 🗌	Yes \square		\$	
_	Other	n/a 🗌	Yes 🗌		\$	
Garage	Singles: repair	n/a ✓	Yes 🗌		\$	
	Shingles: Roof over existing	n/a ☑	Yes 🗌		\$	
	Shingles:Tear off & re-roof	n/a 🗌	Yes ✓		\$	4,360.00
	Gutters/downspouts	n/a	Yes ✓		\$	756.00
	Flashing	n/a ☑	Yes 🗌		\$	
	Eaves	n/a ✓	Yes 🗌		\$	
	Siding	n/a ✓	Yes 🗌		\$	
	Doors	n/a ✓	Yes 🗌		\$	
	Windows	n/a 🗌	Yes ✓		\$	400.00
	Slab	n/a ✓	Yes 🗌		\$	
	Paint	n/a	Yes ✓		\$	1,200.00
	Electrical	n/a ✓	Yes 🗌		\$	
Db	Other	n/a	Yes ✓	address numbers on	alley side \$	25.00
Porches	Roof	n/a ✓	Yes 🗌		\$	
	Deck-upper	n/a ✓	Yes 🗌		\$	
	Decklower	n/a ✓	Yes 🗌		\$	
	Steps/handrails	n/a ✓	Yes 🗌		\$	
	Ceiling	n/a ✓	Yes 🗌		\$	
	Guardrails	n/a ☑	Yes 🗌		\$	
	Structural	n/a ✓	Yes 🗌		\$	
	Paint	n/a ✓	Yes 🗌		\$	

n/a 🗌 Yes 🗌

\$

Other

House

Chimney	n/a ✓ Yes 🗌		\$
Shingles: repair	n/a ☑ Yes □		\$
Shingles: Roof over existing	n/a ☑ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑		\$ 8,720.00
Gutters/downspouts	n/a ☐ Yes ☑		\$ 1,008.00
Flashing	n/a ✓ Yes 🗌		\$
Eaves	n/a ☐ Yes ☑		\$ 425.00
Siding	n/a ☐ Yes ✓		\$ 375.00
Storm Doors	n/a 🗸 Yes 🗌		\$
Prime ("main") Doors	n/a ☐ Yes ✓		\$ 700.00
Storm Windows	n/a ☑ Yes 🗌		\$
Prime ("main") Windows	n/a ☐ Yes ✓ s ı	unroom windows	\$ 500.00
Paint	n/a ☐ Yes ☑		\$ 900.00
Foundation	n/a ☑ Yes 🗌		\$
Electrical	n/a ✓ Yes 🗌		\$
Other	n/a ☐ Yes ☑ w	rindow screens	\$ 250.00
Other	n/a ☐ Yes ☑ re	epair, replace or remove security door	\$ 385.00
Other	n/a ☐ Yes ☑ w	rood trim @ windows	\$ 275.00
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

20,279.00

Interior Co	ondition Report						
	Unit: Entire unit (single family)	✓				Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work	Ш				Other \square	
J	Repair/replace boiler	n/a	V	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a	V	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	V	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	n/a	V	Yes			\$
Electrical	Repair/replace receptacles	n/a		Yes	V		\$ 250.00
	Repair/replace switches	n/a		Yes	V		\$ 250.00
	Repair/replace fixtures	n/a		Yes	V		\$ 250.00
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes	✓	secure junction panel per code	\$ 25.00
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	V	Yes			\$
	Repair/replace kitchen sink fauce	n/a	V	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	V	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	~	Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a	V	Yes			\$
	Unclog piping:	n/a	V	Yes			\$
	Repair drain/waste/vent piping	n/a		Yes	√		\$ 650.00
	Repair water piping	n/a	V	Yes			\$
	Repair/replace water heater	n/a	V	Yes			\$
	Other	n/a		Yes	V	water heater venting	\$ 125.00

Other

2,750.00

Windows										
	Replace broken glass	n/a	V	Yes			\$			
	Repair or replace sash	n/a	V	Yes			\$			
Doors										
	Repair or replace doors	n/a		Yes	J		\$	570.00		
	Repair or repl. locks/latches	n/a		Yes	✓	Self Help	\$	165.00		
Walls/Ceiling			_							
	Repair or repl. @ defective	n/a		Yes	1		\$	3,800.00		
Paint										
	Repair or repl. @ defective	n/a		Yes	√		\$	1,900.00		
Fire Safety										
	Install smoke/CO alarm:bsmt.	n/a		Yes	✓	Self Help	\$	55.00		
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	165.00		
	Install smoke/CO alarm: 2nd flr.	n/a	7	Yes	П	Self Help	\$			
Handrails	-					·	·			
	Repair/replace defective	n/a	V	Yes		Self Help	\$			
Stairs	Repair defective	n/a	П	Yes	V		\$	764.00		
Floors	· ·									
	Repair defective	n/a	J	Yes			\$			
Other		-/-		Vaa	7	misc wood trim	¢.	400.00		
	-	n/a		Yes	⊻	misc wood trim	\$	400.00		
		n/a		Yes			\$			
		n/a		Yes			\$			
		n/a		Yes			\$			
						Interior: Estimated Cost:	\$	12,119.00		
						Total Exterior and Interior Cost:*	\$	32,398.00		
						*average contracted cost. Actual costs may vary. Self help will reduce the amount.				

Inspected by: Tom Frank Date: 9/3/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.